6□□□□□□□□□□□□REH63023

□□□□□□

□□□□□□□□
□□□□□□□□□
□□□□□
□□□ABS
□□□□□□□□□□□□
□□□□□6□□□□□□□□□□
□□□□□REH63023

□□

□□□□□□□□□□□□

The wheelbase

6 AXIS

6 AXIS GYRO

Easy to fly
Automatic
stabilization
system

Barrier shielding

High flexibility

High quality PVC
Such a good
elasticity
Very good
protection

LED lights

Gorgeous
white light
green light

Charging

Aircraft switch in "OFF" state,
aircraft connect USB,
At this point,
the USB light red light

After the connection computer, USB light, charging
USB charging time: 45min.
It is fully charged
when USB light is on.

Charging

TRANSMITTER

□□□□

□□□□□□□□□□□□□□□
□□□□□
□□□□□

□□□□

□□□3.7V 150MAH□□□□□□□□□□□□□
□□□□□□2□* 1.5V
□□□□□□45□□
□□□□□4.5□□
□□□□□30□
□□□30□

□□□□

1□□□□
1□ USB□□
1□ □□□
1□ □□
4□ □□

□□□□□□□□□□□